



ISO QC/DIN 2080

Jacobs/DIN 238 Taper Adaptors




| Taper | Ordering No. | Stock | T | D | L |
|-------|----------------|-------|-----|------|----|
| 30 | QC30-JT6-021 | • | J6 | 17,2 | 21 |
| | QC30-JT33-021 | • | J33 | 15,9 | 21 |
| 40 | QC40-JT6-020 | • | J6 | 17,2 | 20 |
| | QC40-JT33-020 | • | J33 | 15,9 | 20 |
| | QC40-DTB16-013 | • | B16 | 16 | 13 |
| 50 | DT50-JT6-039 | ○ | J6 | 17,2 | 39 |
| | DT50-DTB16-020 | ○ | B16 | 16 | 20 |

ISO Taper Adaptors




| Taper | Ordering No. | Stock | ISO Taper | T | D | L |
|-------|---------------|-------|-----------|-----|----|----|
| 50 | DT50-TA40-060 | • | 40 | M16 | 66 | 60 |

Ancillaries




Quick Change Adaptors




Converts machine spindle to take QC tooling to allow quick tool change overs. All QC30 and QC40 tooling shown in this catalogue can be used in the appropriate adaptor.

| Taper | Ordering No. | Stock | ISO Taper | D | L |
|-------|---------------|-------|-----------|------|----|
| 40 | QC40-QC30-041 | • | QC30 | 76.2 | 41 |
| 50 | DT50-QC40.067 | • | QC40 | 92 | 67 |

Ancillaries



Greenstock Bar Blanks



All blanks have hardened and ground shanks with a plain portion.

| Taper | Ordering No. | Stock | D | L |
|-------|-----------------|-------|----|-----|
| 30 | QC30-BB-045-150 | • | 45 | 150 |
| 40 | QC40-BB-060-160 | • | 60 | 160 |
| 50 | DT50-BB-098-145 | ○ | 98 | 145 |

• = Standard Product - Normally Ex Stock
○ = Standard Product - Availability on Request

Packing unit and ordering example: 1 piece QC30-JT6-021