

SuperaC Slimline Toolholder : MAS 403 BT Form 'A' and 'B'

Form A		Taper	Ordering No.	Stock	d	D1	D2	L1	L2	L3	Lmin
<p>Form B</p> <p>'B' form available Order Example: BT40B – SHYD06-080</p> <p>Dynamically balanced to G2.5 at 20,000 rpm Order example BT40-SHYD06-080G2.5</p> <p>Balanced by Design</p>	40	BT40-SHYD06-080	○	6	26	50	80	38	24	23	
		BT40-SHYD08-080	○	8	28	50	80	38	24	24	
		BT40-SHYD10-080	●	10	30	50	80	40	26	30	
		BT40-SHYD12-090	●	12	32	50	90	45	40	36	
		BT40-SHYD14-090	○	14	34	50	90	45	40	40	
		BT40-SHYD16-090	●	16	38	50	90	50	46	40	
		BT40-SHYD18-095	○	18	40	50	95	52	50	43	
		BT40-SHYD20-095	●	20	42	50	95	52	50	43	
		BT40-SHYD25-105	○	25	53	-	105	59	-	46	
		BT40-SHYD32-110	●	32	60	-	110	60	-	51	
	50	BT50-SHYD06-090	○	6	26	50	90	38	24	23	
		BT50-SHYD08-090	○	8	28	50	90	38	24	24	
		BT50-SHYD10-095	●	10	30	50	95	40	26	30	
		BT50-SHYD12-100	●	12	32	50	100	45	40	36	
		BT50-SHYD14-100	○	14	34	50	100	45	40	40	
		BT50-SHYD16-105	●	16	38	50	105	50	46	40	
		BT50-SHYD18-105	○	18	40	50	105	52	50	43	
		BT50-SHYD20-105	●	20	42	50	105	52	50	43	
		BT50-SHYD25-115	○	25	53	-	115	59	-	46	
BT50-SHYD32-120		●	32	60	-	120	60	-	51		
BT50-SHYD40-125	○	40	68	-	125	65	-	57			
Spare Parts		Pressure Screw	Stopscrew								
		See page 142	See page 142								

● = Standard Product. ○ = Available on request

Packing unit and ordering example: 1 piece BT40-SHYD06-080