

■ Morse Taper Adaptors

Fig 1	TANG TYPE - MT	Taper	Ordering No.	Stock	Fig.	Mt	L	D	T
		40	CV40-MT2-050	•	1	2	050	32	-
			CV40-MB2-050	○	2	2	050	32	M10
			CV40-MT3-070	•	1	3	070	40	-
			CV40-MB3-070	○	2	3	070	40	M12
			CV40-MT4-095	○	1	4	095	48	-
			CV40-MB4-125	○	2	4	125	48	M16
		50	CV50-MT1-050	•	1	1	050	25	-
			CV50-MC2-060	•	3	2	060	32	M10
			CV50-MC3-065	•	3	3	065	40	M12
			CV50-MC4-095	•	3	4	095	48	M16
			CV50-MT5-105	○	1	5	105	70	-
Fig 3	COMBINATION - MC (TANG and DRAWBOLT)								

■ ISO Taper Adaptors

	Taper	Ordering No.	Stock	S ISO Taper	L	D	T
	40	CV40-TA30-040	○	30	40	48	M12
		CV40-TA40-040	○	40	40	70	M16
	50	CV50-TA30-040	○	30	70	48	M12
		CV50-TA40-070	•	40	70	70	M16

■ Spare Parts

Retaining Screws			
See page 141			

CV range available with imperial tapping sizes. Please call for availability.

• = Standard Product - Normally Ex Stock
 ○ = Standard Product - Availability on Request

Packing unit and ordering example: 1 piece CV40-MT2-050