



■ HSK Extension



For adapting HSK tools DIN 69893-1 Form A and C

| Taper | Ordering No. | Stock | L | D | D1 |
|-------------|--------------------|-------|-----|-----|-----|
| 50A | HSK50A-HSK50-080 | • | 80 | 50 | 55 |
| 50A | HSK50A-HSK50-100 | • | 100 | 50 | 55 |
| 63A | HSK63A-HSK63-080 | • | 80 | 63 | 70 |
| 63A | HSK63A-HSK63-120 | • | 120 | 63 | 70 |
| 100A | HSK100A-HSK100-140 | • | 140 | 100 | 110 |
| 100A | HSK100A-HSK100-200 | • | 200 | 100 | 110 |

■ HSK Reducer



For adapting HSK tools DIN 69893-1 Form A and C

| Taper | Ordering No. | Stock | L | D | D1 |
|-------------|-------------------|-------|-----|----|----|
| 50A | HSK50A-HSK32-060 | • | 60 | 32 | 37 |
| 50A | HSK50A-HSK40-070 | • | 70 | 40 | 45 |
| 63A | HSK63A-HSK32-070 | • | 70 | 32 | 37 |
| 63A | HSK63A-HSK40-080 | • | 80 | 40 | 45 |
| 63A | HSK63A-HSK50-080 | • | 80 | 50 | 55 |
| 100A | HSK100A-HSK50-080 | • | 80 | 50 | 55 |
| 100A | HSK100A-HSK63-100 | • | 100 | 63 | 70 |

NOTE:

Coolant supply unit and wrench has to be ordered separately, see page 134
 Assembly comprising clamping cartridge and cover ring.

• = Standard Product - Normally Ex Stock
 ◦ = Standard Product - Availability on Request

Packing unit and ordering example: 1 piece HSK50A-HSK50-080